


JB2



All dimensions have a  $1/32''$  tolerance unless otherwise specified. We do not recommend drilling or cutting any holes before receiving a product or a product sample.