



SIDE VIEW

## NOTE:

ALL DIMENSIONS HAVE A (+/-)  $\frac{1}{16}$ " TOLERANCE UNLESS OTHERWISE SPECIFIED. WE DON'T RECOMMEND DRILLING OR CUTTING ANY HOLES BEFORE RECEIVING A PRODUCT OR A PRODUCT SAMPLE.